

12

AL 1

55

● ●
| |
VÝJIMKA

ZKRAT FK
NENÍ ZÁVADA ●

●

●

Vg 1 = -6 V ●

● Ea = 250 V

● Eg2 = 150 V

●

Vf = 4 V

●

● I = 50 mA

S ≈ 3 mA/V ● PENTODA

50 mA

