

7

6Ц5С

456

6X5C

6BX1

KOLÍK ZASOUVAT  
POSTUPNĚ  
PLUG TO BE PUSHED  
IN SUCCESSIVELY



NEMĚŘIT V POLOZE  
„S“ A „VAKUUM“  
NOT TO BE MEASURED  
IN THE POSITION  
“S” AND “VACUUM”

$E_a = 20 \text{ V}$

$V_f = 6,3 \text{ V}$

$I_a = 150 \text{ mA}$

● DUODIODA  
DUODIODE

150 mA

