


12 ●

AL 4  
AL 3

56 ●

PRO AL 3 ●



●  
G<sub>1</sub>

● V<sub>g1</sub> = -6 V ●

● E<sub>a</sub> = 250 V

● E<sub>g2</sub> = 250 V

●  
V<sub>f</sub> = 4 V ●

● I = 50 mA ●

S ≈ 8 mA/V ● PENTODA

50 mA

