

4

PCC 84

7AN7

30L1

B319

166

A2

KOLÍK ZASOUVAT
POSTUPNĚ

PLUG TO BE PUSHED
IN SUCCESSIVELY



A1

$V_{g1} = -1,5 \text{ V}$

$E_a = 100 \text{ V}$

$V_f = 7,5 \text{ V}$

$I = 50 \text{ mA}$

$S \approx 6 \text{ mA/V}$

TRIODY
TRIODES

50 mA

