


4

PCL85

534



$V_{g1} = -3V$

$E_a = 100V$

$E_{g2} = 100V$

$V_f = 1.8V$

$I = 150mA$

FENTODA

$S = 12mA/V$

